




Drawing

 <b>Hendi B.V.</b> Steenoven 21 3911 TX Rhenen The Netherlands	<b>Batch #</b>	<b>Appliance part#</b>
	0000000	238219
	<b>Description</b>	
	Tepan-Yaki Griddle	

<b>Date</b>	11-03-2013	<b>Revision #</b>	Revision version
<b>Revision</b>	First bill of materials (BOM)		



### Bill of materials (BOM)

 <b>Hendi B.V.</b> Steenoven 21 3911 TX Rhenen The Netherlands	<b>Batch #</b>	<b>Appliance part#</b>
	0000000	238219
	<b>Description</b>	
	Tepan-Yaki Griddle	


<b>Date</b>	11-03-2013	<b>Revision #</b>	Revision version
<b>Revision</b>	First bill of materials (BOM)		

Item	Description	Part#	Quantity	Remark	Picture
1	Grill plate with element 2100W	1	n/a		
2	Lower part foot (right)	2	n/a		
3	Lower part foot (left)	2	n/a		
4	Handle	2	n/a		
5	Foot (left)	2	n/a		
6	Foot (right)	2	n/a		
7	Rubber buffer	4	n/a		
8	Bottom cover	1	n/a		
9	Socket	1	n/a		
10	Removable powercord with variable thermostat	1	928271	150cm	

n/a -> not available

nss -> not sold separately

Circuit diagram

 <b>Hendi B.V.</b> Steenoven 21 3911 TX Rhenen The Netherlands	<b>Batch #</b>	<b>Appliance part#</b>
	0000000	238219
	<b>Description</b>	
	Tepan-Yaki Griddle	

<b>Date</b>	11-03-2013	<b>Revision #</b>	Revision version
<b>Revision</b>	First bill of materials (BOM)		

Not available!!